

**Flood Control Project Maintenance  
Levee Inspections  
LMA District Cover Sheet  
Spring 2010 Levee Inspection Results**

**Reclamation District No. 0349 Sutter Island**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Reclamation District No. 0349 Sutter Island**

Waterway			Bank	Unit Miles
Unit No. 01 Sacramento River			Right	1.59
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/17/2010 - 5/17/2010			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Sacramento River						Right	1.59	05/17/2010 05/17/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.03	Earthen Levee	Encroachments	WS	CO	Landscaping	38.327135 ° -121.577118 °	38.326607 ° -121.577132 °	1 Y
2	0.06	0.82	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.326157 ° -121.577117 °	38.315424 ° -121.579110 °	20
3	0.17	0.70	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.324702 ° -121.577642 °	38.317095 ° -121.579183 °	2 Y
4	0.51	0.66	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.319928 ° -121.578782 °	38.317708 ° -121.579072 °	8
5	1.05	1.09	Earthen Levee	Encroachments	LS	PO	Landscaping	38.312174 ° -121.578490 °	38.311628 ° -121.578271 °	4
6	1.13	1.24	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.311042 ° -121.578103 °	38.309578 ° -121.577250 °	5
7	1.31	1.59	Earthen Levee	Encroachments	LS	PO	Landscaping	38.308790 ° -121.576735 °	38.305123 ° -121.574655 °	6
8	1.43	1.57	Earthen Levee	Encroachments	LS	PO	Landscaping	38.307205 ° -121.575648 °	38.305133 ° -121.574980 °	7
9	1.44	1.48	Earthen Levee	Encroachments	LS	CO	Landscaping	38.307117 ° -121.575524 °	38.306600 ° -121.575210 °	21
10	1.45	1.45	Earthen Levee	Encroachments	LS	PO	Landscaping	38.307075 ° -121.575485 °	38.307073 ° -121.575487 °	17
11	1.56	1.59	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.305580 ° -121.574757 °	38.305210 ° -121.574803 °	19

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.59	05/17/2010 05/17/2010	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.03
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Photo of landscaping at levee mile 0.00- 0.03 waterward.

phillips\_s\_20100615\_073.jpg



Levee Mile Report Line	3
Start Levee Mile	0.17
End Levee Mile	0.70
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Standing on landside at L/M 0.00 Unit 1 looking down stream at slope. Here the weeds are taller than 12". Farther down stream the weeds are taller. 38.327032 -121.577093

phillips\_s\_20100519\_043.jpg



Levee Mile Report Line	3
Start Levee Mile	0.17
End Levee Mile	0.70
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Standing on water side at L/M 0.00 the water side slope at this location is taken over by growth. Looking downstream.

phillips\_s\_20100519\_044.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Reclamation District No. 0349 Sutter Island**

Waterway			Bank	Unit Miles
Unit No. 02 Steamboat Slough			Right	4.35
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/18/2010 - 5/18/2010			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 02 Steamboat Slough						Right	4.35	05/18/2010 05/18/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.03	0.07	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.304935 ° -121.575325 °	38.304798 ° -121.575920 °	2 Y
2	0.04	0.52	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.304853 ° -121.575353 °	38.300055 ° -121.581030 °	3 Y
3	0.04	0.06	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.304873 ° -121.575517 °	38.304873 ° -121.575815 °	1
4	0.10	0.11	Earthen Levee	Encroachments	LS	M	Equipment	38.589334 ° -121.505000 °	38.891916 ° -121.504970 °	967
5	0.14	0.18	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.588764 ° -121.594881 °	38.588187 ° -121.504853 °	968
6	0.16	0.84	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.304042 ° -121.577253 °	38.295734 ° -121.582838 °	969
7	0.21	0.25	Earthen Levee	Encroachments	LS	PO	Landscaping	38.303673 ° -121.578065 °	38.303303 ° -121.578695 °	7
8	0.24	0.27	Earthen Levee	Encroachments	LS	PO	Fences	38.303390 ° -121.578577 °	38.303157 ° -121.578962 °	8
9	0.82	0.82	Earthen Levee	Encroachments	LS	M	Equipment	38.296011 ° -121.582736 °	38.296011 ° -121.582736 °	971
10	0.82	0.83	Earthen Levee	Encroachments	LS	M	Material	38.296005 ° -121.582838 °	38.295862 ° -121.582900 °	67
11	0.82	4.35	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.295958 ° -121.582765 °	38.254793 ° -121.600097 °	4
12	0.84	0.90	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.295753 ° -121.582838 °	38.294985 ° -121.583147 °	12
13	1.06	1.07	Earthen Levee	Encroachments	LS	M	Debris	38.292650 ° -121.583830 °	38.292493 ° -121.583872 °	9
14	1.08	1.31	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.292413 ° -121.583823 °	38.289147 ° -121.583962 °	17
15	1.09	4.35	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.292330 ° -121.583908 °	38.254793 ° -121.600098 °	10
16	1.33	1.34	Earthen Levee	Encroachments	LS	PO	Landscaping	38.288913 ° -121.583933 °	38.288745 ° -121.583938 °	18
17	1.63	1.63	Earthen Levee	Encroachments	LS	M	Tree or limb Inspector Comments: This tree has been on levee slope now since last inspection District is aware of this though they haven't moved.	38.569581 ° -121.515627 °	38.569581 ° -121.515627 °	972 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway							Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough							Right	4.35	05/18/2010 05/18/2010	Herman Phillips
LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
18	1.80	1.83	Earthen Levee	Encroachments	LS	CO	Landscaping	38.283698 ° -121.589143 °	38.283400 ° -121.589273 °	25
19	2.41	2.44	Earthen Levee	Encroachments	LS	PO	Landscaping	38.275492 ° -121.591268 °	38.275092 ° -121.590910 °	31
20	2.70	2.72	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.272228 ° -121.589695 °	38.272017 ° -121.589818 °	34
21	2.77	3.02	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.271213 ° -121.589877 °	38.267830 ° -121.588897 °	36
22	3.07	3.10	Earthen Levee	Encroachments	LS	CO	Landscaping	38.267265 ° -121.588470 °	38.266747 ° -121.588355 °	38
23	3.16	3.18	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.265783 ° -121.588377 °	38.265495 ° -121.588376 °	973
24	3.41	3.47	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.262669 ° -121.589830 °	38.262699 ° -121.590920 °	974
25	3.64	3.72	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.262322 ° -121.593935 °	38.261483 ° -121.594867 °	43
26	3.73	3.74	Earthen Levee	Encroachments	WS	PO	Landscaping	38.261403 ° -121.594932 °	38.261330 ° -121.595022 °	45
27	3.75	3.77	Earthen Levee	Encroachments	LS	M	Equipment	38.261242 ° -121.595173 °	38.260868 ° -121.595267 °	47
28	3.75	3.75	Earthen Levee	Encroachments	LS	M	Tree or limb	38.261070 ° -121.595060 °	38.261070 ° -121.595060 °	975
29	3.78	3.78	Earthen Levee	Encroachments	LS	M	Tree or limb	38.260823 ° -121.595253 °	38.260705 ° -121.595275 °	48
30	3.84	3.86	Earthen Levee	Encroachments	LS	PO	Fences	38.259707 ° -121.595275 °	38.259943 ° -121.595380 °	11
31	4.29	4.35	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.254846 ° -121.599030 °	38.254796 ° -121.600093 °	976
32	4.34	4.35	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.254760 ° -121.599925 °	38.254880 ° -121.600070 °	81

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Steamboat Slough	Right	4.35	05/18/2010 05/18/2010	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.03
End Levee Mile	0.07
Location	Water Side
Category	Earthen Levee
Item	Vegetation

This picture shows the growth on waterward slope. This growth is present through the Unit. This marks the beginning of unit 2.

phillips\_s\_20100616\_079.jpg



Levee Mile Report Line	2
Start Levee Mile	0.04
End Levee Mile	0.52
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shows growth on levee slopes landward although the weeds here are taller than 12-inches, it does not block visibility of the levee. This growth is consistent through this unit.

phillips\_s\_20100616\_078.jpg



Levee Mile Report Line	17
Start Levee Mile	1.63
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Encroachments

This tree was on the levee slope during my last inspection, the District has been told to remove it, it still remains today. No attempt has been made to remove.

phillips\_s\_20100520\_045.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor



**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2010 Levee Inspection Results**

**Reclamation District No. 0349 Sutter Island**

Waterway			Bank	Unit Miles
Unit No. 03 Sutter Slough			Left	6.55

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/18/2010 - 5/20/2010			
DWR Inspector	Herman Phillips			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

**Comments**

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 03 Sutter Slough						Left	6.55	05/18/2010 05/20/2010	Herman Phillips	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	1.08	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.254830 ° -121.600128 °	38.269977 ° -121.603520 °	1 Y
2	0.01	1.15	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: There is a picture that was taken that will show the growth on the levee section viewed from levee mile 0.01 facing downstream on the water side.	38.254798 ° -121.600133 °	38.270915 ° -121.603570 °	2 Y
3	0.62	0.62	Earthen Levee	Trim / Thin Trees	LS	N	Tree stumps.	38.263622 ° -121.601080 °	38.263622 ° -121.601080 °	5 Y
4	0.63	0.63	Earthen Levee	Trim / Thin Trees	LS	N	Tree stumps.	38.263757 ° -121.601070 °	38.263757 ° -121.601070 °	3 Y
5	0.79	0.85	Earthen Levee	Encroachments	LS	CO	Landscaping	38.265952 ° -121.601692 °	38.266842 ° -121.602033 °	4
6	0.97	0.97	Earthen Levee	Encroachments	WS	M	Tree or limb	38.268393 ° -121.602911 °	38.268393 ° -121.602911 °	971
7	1.11	1.12	Earthen Levee	Encroachments	LS	M	Tree or limb	38.270247 ° -121.603575 °	38.270477 ° -121.603527 °	18
8	1.23	1.73	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.272225 ° -121.603195 °	38.278770 ° -121.600230 °	6
9	1.29	1.73	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.272827 ° -121.602895 °	38.278773 ° -121.600228 °	7
10	1.70	1.76	Earthen Levee	Encroachments	LS	CO	Landscaping	38.278355 ° -121.600330 °	38.279095 ° -121.600273 °	14
11	1.86	6.41	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.280655 ° -121.600588 °	38.328380 ° -121.378410 °	8
12	1.99	6.41	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.282328 ° -121.601582 °	38.328383 ° -121.378410 °	9
13	2.51	3.98	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.289215 ° -121.603322 °	38.288622 ° -121.603298 °	10
14	4.10	4.10	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.308990 ° -121.597693 °	38.308990 ° -121.597693 °	11
15	5.25	6.41	Earthen Levee	Vegetation	CR	M	Control annual grass and weeds on the levee slopes and easements.	38.322700 ° -121.589357 °	38.328383 ° 121.578410 °	13
16	6.06	6.11	Earthen Levee	Encroachments	LS	C	Tree or limb Inspector Comments: This brush pile needs to be burned or not allowed to remain on the levee section.	38.331563 ° -121.583342 °	38.331460 ° -121.582448 °	973

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough				Left	6.55	05/18/2010 05/20/2010	Herman Phillips

  

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
17	6.39	6.41	Earthen Levee	Encroachments	WS	C	Firewood Inspector Comments: The farmer has declared this section of levee as his burn pile. If he plans to burn then this should be burned or removed from the levee, rodents will start to dig holes under the brush piles.	38.328762 ° -121.578890 °	38.328383 ° -121.578408 °	972

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.55	05/18/2010 05/20/2010	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Vegetation

This photo shown here is a sampling of what the land side growth looks like through this unit, however there are some sections where the growth is much taller. Standing here at levee mile 0.00 looking downstream.

phillips\_s\_20100617\_080.jpg



Levee Mile Report Line	2
Start Levee Mile	0.01
End Levee Mile	1.15
Location	Water Side
Category	Earthen Levee
Item	Vegetation

Standing here on the water ward side of the levee at levee mile 0.01 looking down stream, tall weeds are viewed on levee slopes.

phillips\_s\_20100617\_081.jpg



Levee Mile Report Line	3
Start Levee Mile	0.62
End Levee Mile	0.62
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

This stump is located on the landward slope.

phillips\_s\_20100616\_076.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected  
W : Watch/Monitor

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2010**

**Reclamation District No. 0349 Sutter Island**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Sutter Slough	Left	6.55	05/18/2010 05/20/2010	Herman Phillips

Levee Mile Report Line	4
Start Levee Mile	0.63
End Levee Mile	0.63
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees

Broken tree with stump on landward slope, broken top portion of this tree is resting on the landward toe. District is aware of this encroachment.

phillips\_s\_20100616\_077.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing      W : Watch/Monitor  
U : Unacceptable      N : Not Inspected